


CONNECTION DIAGRAM when using Evolution inj. model ignition coil OEM 31639-95



Crank-Sensor, located at the front left side of the crank-case. The only sensor, to connect.

**WARNING!**

Persons with heart diseases shall not install or maintenance this ignition system!

Do not overtighten terminal screws. Please take care, that there are no short circuits between the cables.

During installation keep the ignition coil disconnected from the P3 ignition in order to prevent dangerous voltages. Never use this ignition system without ignition cables and spark-plugs properly connected! This diagram is for EFI coil 31639-95. If you use a different ignition coil, please refer to the corresponding diagram.